

# NEW PRODUCT HIGHLIGHT | APR2019



## febi 102601

to fit:  
MINI, BMW, Vauxhall, Opel, Peugeot,  
Citroen, DS. Various Models



EN

### Tensioner Assembly

#### Function

The water pump fitted to these vehicles is controlled by the engine management system with this electronic tensioner assembly. When engaged it transmits power from the crankshaft pulley to the water pump pulley, which controls the flow of coolant. This makes the engine more thermally efficient, reduces emissions and improves fuel efficiency.

#### Failure

This component can suffer from squeaking or from seized drive bearings, which can fail over time. When replacing the component it is advised to check and replace the auxiliary belt and the water pump pulley

For more technical information please visit: [partsfinder.bilsteingroup.com](http://partsfinder.bilsteingroup.com)