

SERVICE INFO



Design change affecting tensioning pulley 531 0779 10

Vehicle

manufacturers: Alfa Romeo, Fiat, Opel, Vauxhall

Models:

Alfa Romeo: 159

Fiat: Cromia

Opel: Astra G, Astra H, Corsa D, Meriva, Signum, Vectra C

Vauxhall: Astra Mk V, Meriva, Vectra Mk II, Zafira Mk II

Engine:

939 A4.000, Z16XER, Z16XEP, Z18XER, Z18XEP, Z16LEL, Z16LER, Z16LET

Part No.:

531 0779 10



Image 1: Front view of the previous model




Image 2: Front view of the new model



Image 3: Rear view of the previous model



Image 4: Rear view of the new model

Due to the constant development of our products, the design of tensioning pulley 531 0779 10 has been changed. The Service Information sheet shows the visual differences between the two designs (see Images 1 to 4).

We may have mixed stocks during the transitional phase.

Both tensioning pulleys meet the technical specifications and can be used without restrictions on the specified vehicles.

Note:

Please use a 6-mm hexagon allen key to turn the cam and tension the toothed belt with modified tensioning pulley.

Note:

Please observe the installation instructions for the modified tensioning pulley included in the packaging!



Note the specifications of the vehicle manufacturer!

Appropriate spare parts can be found in our on-line catalogue at www.Schaeffler-Aftermarket.com or in RepXpert at www.RepXpert.com.

Issued 02.2011

INA 0068

Subject to technical changes

© 2011 Schaeffler Automotive Aftermarket

Any reference to replacement part numbers for vehicle manufacturers is for comparison purposes only.

For further information:

Phone: +44 (0) 14 32 264 264*

Fax: +44 (0) 14 32 375 760

Info@LuK-AS.co.uk

www.Schaeffler-Aftermarket.com

* Calls from within the UK 08457 001100

