



Service Info



Deflection pulley 532 0833 10

The supplied screw must be used

Manufacturer: Subaru

Models: Forester, Impreza, Legacy, Outback

Engines: 1.5, 2.0, 2.5

Part no.: 532 0833 10
530 0522 09
530 0522 10
530 0563 10

For current listing refer to catalogue media



Photo: 532 0833 10 – INA deflection pulley with supplied screw

When installing deflection pulley 532 0833 10 (see photo), the supplied screw must be used.

The screw installed by the vehicle manufacturer is too long for fastening deflection pulley 532 0833 10. As a result, it is impossible to install the pulley correctly using the original screw.

Use of an unsuitable screw can cause the timing drive to fail and result in engine damage.

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264*

Fax: +44 (0) 1432 375 760

hfd-info@schaeffler.com

www.schaeffler-aftermarket.co.uk

* Calls from within the UK 08457 001100

