



Service Info



Use supplied screws

Coolant pump housing has been modified

Manufacturer: Ford

Models: C-Max, Fiesta, Focus, Mondeo, S-Max, Transit

Engines: 1.8 TDCI

Part no.: 538 0256 10

For current listing refer to catalogue media



Fig. 1: Contents of the coolant pump package




Fig. 2: Modified mounting points of the coolant pump

The housing of coolant pump 538 0256 10 has been modified. As a result, the screws (M6x37) supplied with the pump absolutely must be used at the three mounting points indicated (Fig. 2).

The increased material thickness at the three mounting points necessitates the use of these longer screws.

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264*

Fax: +44 (0) 1432 375 760

hfd-info@schaeffler.com

www.schaeffler-aftermarket.co.uk

* Calls from within the UK 08457 001100



SCHAEFFLER

REP>XPERT