



Service Info



Belt tensioner 534 0250 10

Visual differences

Manufacturers: Citroën, Peugeot

Models:

Citroën: C2, C3, C4, C-Elysee

Peugeot: 206, 207, 301, 307, 308, 1007

Engines: 1.1, 1.4, 1.6

Part no.: 529 0070 10

529 0071 10

534 0250 10

For current listing refer to catalogue media




Figure 1: Previous design




Figure 2: New design

As part of our continuous efforts to improve our products, modifications have been made to the belt tensioner with part number 534 0250 10.

This Service Information sheet shows the visual features of the previous version (Figure 1) and the new version (Figure 2).

During the transition period, we may have mixed stocks of both types.

The two versions differ only in their appearance. Both comply with the technical specifications and can be used without restrictions.

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264*

Fax: +44 (0) 1432 375 760

hfd-info@schaeffler.com

www.schaeffler-aftermarket.co.uk

* Calls from within the UK 08457 001100



SCHAEFFLER

REP>XPERT