

SWAG 50 93 2418 83 10 3186

SWAG[®]

To Fit:
Ford, Mazda and Volvo various models



EN

Control Arm Bush

Problem

Uneven tyre wear and misaligned front suspension.

Cause

Worn lower suspension control arm control bush.

Solution

SWAG provides an economical repair solution; the control arm bush can be replaced instead of replacing the complete suspension control arm. When replacing this bush it is important that the alignment of the original control arm bush be followed. If the bush is not aligned correctly on the shaft of the suspension arm, there is a risk of premature failure and a shortened lifetime of the component.

There is a special tool available from the vehicle manufacturer to assist in the replacement of the control arm bush.

By using this tool, it can be ensured that the installation position and press-fit depth of the bush will be correct.

For more technical information please visit: partsfinder.bilsteingroup.com