



Service Info



Visual differences

in over-running alternator pulley 535 0240 10

Manufacturer: Toyota

Model: Auris, Corolla, Verso S, Yaris

Engine: 1.4 D4-D

Part no.: 535 0240 10

OE number: 27415-33070



Figure 1: Previous design



Figure 2: New design

As part of our continuous efforts to improve our products, modifications have been made to the over-running alternator pulley with part number 535 0240 10.

This Service Information sheet shows the visual features of the previous version (Figure 1) and the new version (Figure 2).

During the transition period, we may have mixed stocks of both types.

The two versions differ only in their appearance. Both comply with the technical specifications and can be used without restrictions.

Observe the specifications of the vehicle manufacturer!

Spare parts and technical information can be found under www.schaeffler-aftermarket.com or www.RepXpert.com.

Phone: +44 (0) 14 32 264 264*
 Fax: +44 (0) 14 32 375 760
hfd-info@schaeffler.com
www.schaeffler-aftermarket.com

* Calls from within the UK 08457 001100

SCHAEFFLER
 AUTOMOTIVE AFTERMARKET

